



DISCONTINUED OGIO® Cadmium Jacket. OE502




LUX COTTON-RICH SOFTNESS
LAYERABLE WARMTH
STRETCH
FLATLOCK SEAMS FOR COMFORT
REFLECTIVE DETAILS

- 4.3-ounce, 56/38/6 French terry cotton/poly/spandex
- Reflective OGIO heat transfer label for tag-free comfort
- 3-panel hood
- Zip-through collar with chin guard
- Metalux zipper with molded cord pull
- Set-in sleeves
- Reflective O heat transfer at right back shoulder
- Lower front pockets
- Reflective O heat transfer at left pocket
- 2x2 flat knit cuffs and hem

CARE INSTRUCTIONS

Machine wash cold with like colors. Do not bleach. Tumble dry low. Warm iron if necessary




front



back

HOW TO MEASURE



CHEST WIDTH
Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

SIZE CHART

	XS	S	M	L	XL	2XL	3XL	4XL
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57

COLOR INFORMATION